

# BREWER'S EDGE® 1/2 MICRON OXYGEN AERATOR

## WARNING!

Wear safety glasses when using. Keep away from fire and flame. For wort aeration purposes only, not for brazing, welding, human consumption, or life support use.

## Assembly

Slip the Aeration Tubing over the Oxygen Regulator Outlet Nipple and over the Aerating Wand. Now purchase a 1.4 or 2.1 ounce left-hand thread oxygen bottle at any hardware store (welding or brazing section, Worthington® or Bernzomatic® brand). Now thread on the regulator (counter clockwise to attach) and your Aeration System is complete.



## To Use

To aerate 5 gallons of wort to 70% of its oxygen holding capacity (a good level for quick yeast growth), sanitize the wand and dip into 5 gallons of freshly made cooled wort. Turn on the regulator until you see steady bubbling (not a huge bubbling spurt), and keep it going for 20 seconds. Move the wand around in the wort to distribute the oxygen. Turn off and remove, and your wort is ready for yeast. Aeration becomes more important as the starting gravity of the wort increases.

## Cleaning & Storage

Avoid handling of the stone end, as oils on your fingers can contribute to clogging. Soak the stone end of the wand in a dilute sanitizing solution. Rinse and air dry. If you want to sanitize the stone without chemicals, boil it for 10 minutes in water.

Contains:

- 1 Q11 Oxygen Regulator
- 4' Q26 1/8" Tubing
- 1 Q08 1/2 micron 22" Aeration Wand

All Parts Made In U.S.A.